

0011

Outgoing  
C0070006  
Q

**From:** Steve Demczak  
**To:** Dennis Ware; Suzanne Steab  
**Date:** 4/1/2010 12:47 PM  
**Subject:** March Insp.  
**Attachments:** 20100401120323.pdf; 20100401120345.pdf; 20100401120307.pdf



The State of Utah

Department of  
Natural Resources

Division of  
Oil, Gas & Mining

ROBERT L. MORGAN  
*Executive Director*

LOWELL P. BRAXTON  
*Division Director*

OLENE S. WALKER  
*Governor*

GAYLE F. McKEACHNIE  
*Lieutenant Governor*

Representatives Present During the Inspection:

Company Dennis Ward President

OGM Steve Demczak Environmental Scientist III

## Inspection Report

Permit Number:	C0070006
Inspection Type:	PARTIAL
Inspection Date:	Tuesday, March 23, 2010
Start Date/Time:	3/23/2010 1:00:00 PM
End Date/Time:	3/23/2010 4:00:00 PM
Last Inspection:	Thursday, February 25, 2010

Inspector: Steve Demczak, Environmental Scientist III

Weather: Windy, 30's, Sunny

InspectionID Report Number: 2315

Accepted by: jhelfric  
4/1/2010

Permitee: **PLATEAU MINING CORP**

Operator: **PLATEAU MINING CORP**

Site: **STAR POINT MINE**

Address: **PO BOX 30, HELPER UT 84526-0030**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **RECLAIMED**

Current Acreages

8,919.91	Total Permitted
113.34	Total Disturbed
113.34	Phase I
95.30	Phase II
5.64	Phase III

Mineral Ownership

- ☒ Federal  
☒ State  
☐ County  
☒ Fee  
☐ Other

Types of Operations

- ☒ Underground  
☐ Surface  
☐ Loadout  
☐ Processing  
☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

No violations were issued.

Inspector's Signature: \_\_\_\_\_

*Steve Demczak*  
Steve Demczak, Environmental Scientist III

Inspector ID Number: 39

Date Wednesday, March 31, 2010

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801  
telephone (801) 538-5340 facsimile (801) 359-3940 TTY (801) 538-7223 [www.ogm.utah.gov](http://www.ogm.utah.gov)

**Utah!**  
Where ideas connect™

Permit Number: C0070006  
 Inspection Type: PARTIAL  
 Inspection Date: Tuesday, March 23, 2010

## Inspection Continuation Sheet

Page 2 of 3

### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

**2. Signs and Markers**

The identification signs is next to the road to the site.

**3. Topsoil**

All topsoil was used for reclamation.

**4.a Hydrologic Balance: Diversions**

Some diversions were snow covered. The diversions facing south were open and would function as design.

**4.c Hydrologic Balance: Other Sediment Control Measures**

The site is pocked to control sediment.

**8. Noncoal Waste**

The reclaim site is clear of non-coal waste material.

**10. Slides and Other Damage**

No slides or other damage could be seen from the main road at the old refuse pile.

**12. Backfilling And Grading**

The site is completely backfilled and graded.

**18. Support Facilities, Utility Installations**

There are no facilities.